

Metal worm-drive clamp displays



Description	
Reference	Includes
DEPANNE 244	<p>244 worm-drive clamps: - 100 mini type PBM: 10 x PBM 8 / 10 x PBM 9 / 10 x PBM 10/ 10 x PBM 11 / 10 x PBM 12 / 10 x PBM 13 / 10 x PBM 14 / 10 x PBM 15 / 10 x PBM 16 / 10 x PBM 17 - 144 standard PBS: 12 x PBS9 814 / 12 x PBS9 1117 / 12 x PBS9 1320 / 24 x PBS9 1524 / 12 x PBS9 1928 / 12 x PBS9 2232 / 12 x PBS9 2638 / 12 x PBS9 3244 / 12 x PBS9 3850 / 12 x PBS9 4456 / 12 x PBS9 5065 - 1 flexible worm driver: PB 3000</p>
DEPANNE 400	<p>400 worm-drive clamps: - 100 mini type PBM: 10 x PBM 8 / 10 x PBM 9 / 10 x PBM 10 / 10 x PBM 11 / 10 x PBM 12 10 x PBM 13 / 10 x PBM 14 / 10 x PBM 15 / 10 x PBM 16 / 10 x PBM 17 - 300 standard PBS: 25 x PBS9 814 / 25 x PBS9 1117 / 25 x PBS9 1320 / 50 x PBS9 1524 / 25 x PBS9 1928 / 25 x PBS9 2232 / 25 x PBS9 2638 / 25 x PBS9 3244 / 25 x PBS9 3850 / 25 x PBS9 4456 / 25 x PBS9 5065 - 1 flexible worm driver: PB 3000</p>

