


Quick release claw - Blanking plug



| | | | |
|---|---|---|---|
| <p><u>Description</u> Blanking plug</p> | <p><u>Max operating pressure</u> 10 bar</p> | <p><u>Temperature</u> -5°C to +60°C</p> | <p><u>Construction</u> Brass body</p> |
|---|---|---|---|

| Description | |
|-------------|---------------|
| Reference | Description |
| EXP BRE | Blanking plug |



Dimensions

| Reference | A mm | B mm |
|----------------|------|------|
| EXP BRE | 57 | 30 |