


Quick release claw - Blanking plug



<p><u>Description</u> Blanking plug</p>	<p><u>Max operating pressure</u> 10 bar</p>	<p><u>Temperature</u> -5°C to +60°C</p>	<p><u>Construction</u> Brass body</p>
---	---	---	---

Description	
Reference	Description
<p>EXP BRE</p>	<p>Blanking plug</p>



Dimensions

Reference	A mm	B mm
EXP BRE	57	30