


Quick release claw - Blanking plug



<p><u>Description</u> Blanking plug</p>	<p><u>Max operating pressure</u> 10 bar</p>	<p><u>Temperature</u> -5°C to +60°C</p>	<p><u>Construction</u> Brass body</p>
---	---	---	---

Description	
Reference	Description
EXP BRE	Blanking plug



Dimensions

Reference	A mm	B mm
EXP BRE	57	30